
B+UNFUSED
B+FUSED
B+FUSED
+SLAVE BASE
+BIAS
+COLLECT.
+DRIVE
CURRENT SENSE
FEEDBACK
-DRIVE
-COLLECT
-BIAS
-SLAVE BASE
B-FUSED
B+FUSED
B-UNFUSED
INPUT
1.66VAC
BOARD # GAS 121F
OUTPUT
BOARD # GAS 123F